BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W1985, W1983, W1268, W1266, W1264, W1987	1st Main Rd 5th Crs Bank Avenue Horamavu, C M R Colony Rd, 6th Crs, NA, 2nd Main Rd 5th Crs Bank Ave	Nagawara colony
Segment No.	**Total Length (m)**	
6/C-W1985/S035239	106.96	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	73.36	77.623306	13.039665	77.623981	13.039644	Nagawara colony	cross road
2	33.60	77.623593	13.039853	77.623574	13.039550	Nagawara colony	cross road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Package-1 includes 3 works of Rs.100.00 lakhs 1) Providing Cement Concrete Roads at nagawara Colony in Ward No. 06 Byatarayanapura Sub Division. 2) A	10000000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Others	Rcc drain, CC road and culverts
Tender	**Work Details**	**Job No. / Work Code**
Tender	Rcc drain, CC road and culverts	006-18-000032
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/206/2018-19	04/01/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
22/02/2019	22/02/2022	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Shri Lakshmi infra india Pvt Ltd.		0.00
Phone No.	**E-Mail ID**	

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-26

9844426603

Field Inspection Details

Number of Trees	Any Other Information	Name
0		daramsingh

Date of Inspection	Remarks
06/06/2019	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.A.B.Doddaiah	11/06/2019	06/07/2019	As proposed
SE	Basavaraj R Kabade	10/06/2019	06/07/2019	forwarded
EE	Mohandas H T	06/06/2019	06/07/2019	approved
AEE	sridhar	06/06/2019	06/07/2019	Verified
AE	Daramsingh	06/06/2019	06/07/2019	Mobile Verification is done
AE	Daramsingh	06/06/2019	06/07/2019	Forward

Zone: YELAHANKA Ward No: 6 Ward Name: Thanisandra Street ID: W1985, W1983, W1268, W1266,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-24

Bruhat Bengaluru Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W0015, W0028, I0128, W0026	NA	Manjunatha layout
Segment No.	**Total Length (m)**	
6/C-W0015/S034508	145.73	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	145.73	77.627659	13.068450	77.627508	13.067141	manjunatha layout	main road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Package-1, includes 3 works of Rs.100.00 lakhs 1) Providing Cement Concrete Roads at nagawara Colony in Ward No. 06 Byatarayanapura Sub Division. 2) A	10000000	207-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Others	RCC Drain, CC road and culverts
Tender	**Work Details**	**Job No. / Work Code**
Tender		006-18-000032
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/206	04/01/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
04/01/2019	04/01/2021	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Shri Lakshmi infra india Pvt Ltd.		0.00
Phone No.	**E-Mail ID**	
9844426603		

Zone: YELAHANKA Ward No: 6 Ward Name: Thanisandra Street ID: W0015, W0028, I0128, W0026

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು-26

Field Inspection Details

Number of Trees	Any Other Information	Name
0		daramsingh

Date of Inspection	Remarks
06/06/2019	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range
Drain Condition		This photo seems out of range
Road Condition		This photo seems out of range

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri A.B Doddaiah	11/06/2019	06/07/2019	As proposed
SE	Basavaraj R Kabade	10/06/2019	06/07/2019	forwarded
EE	Mohandas H T	06/06/2019	06/07/2019	approved
AEE	Sridhar	06/06/2019	06/07/2019	Verified
AE	Daramsingh	06/06/2019	06/07/2019	Mobile verification is done
AE	Daramsingh	06/06/2019	06/07/2019	Forwarded

Zone: YELAHANKA Ward No: 6 Ward Name: Thanisandra Street ID: W0015, W0028, I0128, W0026

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-24